

# **POLE GUARD TEST REPORT**

Client:Transnet LtdSite Contact:Spencer WinnLocation:East TamakiReport No.:RG120816

Test Date: 12<sup>th</sup> August 2016 Job Number: N/A 90 Lady Ruby Drive PO Box 204-224 Highbrook Auckland Ph: 0800 935674 Fax: +64 9 271 0351

This report is produced to meet the requirements requested by the customer.

### **Product Details:**

Make:	Marino Plas	Intended Voltage:	=<33kV
Size:	2.7m x 150 x 150mm	Product Code:	PC2700x150x150

# Test Results:

Test Number	Voltage	Duration	Leakage Current	Pass / Fail
1	10kV	One Minute	2.8mA	Pass
2	20kV	One Minute	6.6mA	Pass
3	30kV	One Minute	10mA	Pass
4	40kV	One Minute	16mA	Pass

## Comment from Results:

New Manufactured Unit. Guard will not allow any further applied voltage due to size and required "gap distance" for higher voltages.

PASS

#### **Overall Result:**

Ross Gamble General Manager